## LICENSEE EVENT REPORT

CICENSEE EVENT HET ON
CONTROL BLOCK:
0 1 P A B V S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 5
O T SOURCE L 6 0 5 0 0 0 3 3 4 7 1 1 2 6 8 0 8 1 2 1 0 8 0 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [3 2 At 1120 hours on November 26, a special investigation being conducted in response to
The Publishing 70-1/ found that an overstressed condition existed on the Low Head
Safety Injection (LHSI) pumps discharge relief lines. It was determined that a
0 5   modification was required to allow the line movement in the direction of thermal
[0]6]   expansion. The plant was at about 35% reactor power when Technical Specification
0 7 3.03 was invoked. Any additional details will be reported in the final IE Bulletin
0 8 1 79-14 report.
7 8 9  SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
S F 10 B 12 A 13 S U P O R T 14 B 15 Z 16  SEQUENTIAL OCCURRENCE REPORT REVISION
17 REPORT   8   0   -   0   8   8   -   0   1   T   -   0   32   11   32   12   12   12   13   14   15   15   15   15   15   15   15
TAKEN ACTION FUTURE CAPPLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB.  F 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 Z 25 Z 19 9 9 9 9 2 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
No cause description is known at this time. Immediate steps were taken directing
1111   how to operate the LHSI pumps in the event of an accident and to remove
restrictions on pipe thermal expansion. These steps were designed to ensure a safe
system condition until permanent modifications could be completed. At 1235 hours
on November 26, these modifications were verified as complete.
FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION (32)    1   5   F   28   0   3   5   29   N/A   C   31   Special investigation   80
ACTIVITY CONTENT RELEASED OF RELEASE  AMOUNT OF ACTIVITY 35  N/A  N/A  80
PERSONNEL EXPOSURES  NUMBER  TYPE  OESCRIPTION (39)  N/A
7 8 9 PERSONNEL INJURIES 13
1 3 0 0 0 40 N/A
LOSS OF OR DAMAGE TO FACILITY (13)  VANCE DESCRIPTION N/A  N/A
PUBLICITY ISSUED DESCRIPTION 45  N/A  N/A
68 69 80 1 S Tacey 412-643-8525
NAME OF PREPARER W. S. Lacey PHONE:

Attachment To LER 80-88/01T Beaver Valley Power Station Duquesne Light Company Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.