

Georgia Power Company
230 Peachtree Street
Post Office Box 4549
Atlanta, Georgia 30302
Telephone 404 320-6000

TIC

R. J. Kelly
Assistant Director
Public Policy Division

December 1, 1980

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 3100
101 Marietta Street, NW
Atlanta, Georgia 30303

REFERENCE:
RII JPO
50-321/50-366
I&E Bulletin 80-24


ATTENTION: Mr. James P. O'Reilly

Gentlemen:

I&E Bulletin 80-24 requests licensees to conduct interim surveillance measures inside containment to check for water leakage. Edwin I. Hatch Unit 1 has an open cooling system. However, due to radiation levels and inerting of the containment entry during operation is impractical. Therefore, a containment inspection for water leakage will be performed at the first cold shutdown of Unit 1.

If you have any further questions, please contact this office.

Sincerely yours,


R. J. Kelly

013
DLT/mb

xc: Director of the Office of Inspection and Enforcement
Director of the Division of Operating Reactors, Office of
Nuclear Reactor Regulation
M. Manry
R. F. Rogers, III

REGISTRATION
SERVICES UNIT

1980 DEC 12 AM 10 33

U.S. NRC
DISTRIBUTION SERVICES
BRANCH

8012230064