

APPENDIX A

NOTICE OF VIOLATION

Philadelphia Electric Company

Docket Nos. 50-277
50-278

Based on the results of an NRC inspection conducted on October 1 - November 7, 1980, it appears that one of your activities was not conducted in full compliance with conditions of your NRC License Nos. DPR-44 and DPR-56 as indicated below. This is an infraction.

10 CFR 50, Appendix B, Criterion VI states in part:

"Measures shall be established to control the issuance of documents, such as instructions, procedures, and drawings, including changes thereto... these measures shall assure that documents... are distributed to and used at the location where the activity is performed." The licensee's NRC accepted Quality Assurance Plan, Volume III, Section 2, paragraph 6.1 states in part:

"documents, including changes... are distributed to and used at the location where the prescribed activity is performed."

Contrary to the above, as of October 21, 1980 the current revision of procedure SE-1, "Plant Shutdown from Outside the Control Room," was not posted at the Emergency Shutdown Panels, the location of performance of the prescribed activities. (Recurrent Item)

B108180 177