

MAY 28 1981



Northwest Airlines
ATTN: Mr. George Dalin
Minneapolis - St. Paul
International Airport
Main Overhaul Base
St. Paul, MN 55111

License No. 22-12080-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on May 14 and 15, 1980, of activities authorized by NRC Byproduct Material License No. 22-12080-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated July 19, 1979 regarding apparent items of noncompliance found during our June 22, 1979, inspection. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Acting Chief
Materials Radiation Protection
Section 1

cc: DMB/Document Control Desk (RIDS)

1E07
5/10

RIII
Gibbons/db
5/21/81

RIII
Wiedeman
5/28/81

8106050 443