TENNESSEE VALLEY AUTHORITY

CHATTANOOGA. TENNESSEE 37401

1750 Chestnut Street Tower II

September 26, 1980

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFRO-50-259/8069

The enclosed report provides details concerning channel "B" of modulating damper 0-PDC 64-8 which failed to close. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoum Director of Nuclear Power

Enclosure (3)
cc (Enclosure):
 Director (3)
 Office of Management Information and Program Control
 U.S. Nuclear Regulatory Commission
 Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

POOR ORIGINAL

8009 300 516 5

A002