


Georgia Power Company
230 Peachtree Street
Post Office Box 4345
Atlanta, Georgia 30302
Telephone: 404 522-8060

TIC 10

W. A. Widner
Vice President and General Manager
Nuclear Generation

March 5, 1981



U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 3100
101 Marietta Street, NW
Atlanta, Georgia 30302

REFERENCE:
RII: JPO
~~50-351/50-366~~
I&E Bulletin 79-01B

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

This letter transmits Georgia Power Company's (GPC) update of its I&E Bulletin 79-01B response as committed to in a letter to your office dated February 17, 1981.

The update covers the portions of GPC's response affected by the delay in implementing the schedule for installing qualified limit switches and solenoids on Unit 2 during the recent refueling outage. It also provides a justification for continued operation considering the main steam isolation valves limit switch installations as inadequate. In addition, since other valve limit switch installations have now been listed as inadequate, the generic justification for limit switches used for position indication, but which lack adequate documentation, is applicable to these situations. GPC is also taking this opportunity to correct some typographical and other miscellaneous errors discovered in the February 1, 1981, submittal.

This package contains the amended pages along with instructions for correctly updating the GPC I&E Bulletin 79-01B response.

GPC hopes this information is useful in helping your staff follow the implementation of the subject bulletin.

If you have any questions or comments, please contact this office.

Sincerely,

W. A. Widner

DLT/mb

Attachment

Q 8103260 503