

TR

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

40

April 1, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-23 - RIT:JPO
50-518, -519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND
NUCLEAR PLANTS

In response to your November 14, 1980, letter to H. G. Parris which transmitted OIE Bulletin 80-23, we are enclosing the final report on our investigations for the Hartsville and Phipps Bend Nuclear Plants. If you have any questions, please call Jim Domer at FTS 857-2014.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager

Nuclear Regulation and Safety

Enclosure

cc: Office of Inspection and Enforcement (Enclosure)
U.S. Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Washington, DC 20555

Q 8104140 604

ENCLOSURE

FINAL RESPONSE TO IE BULLETIN 80-23
HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS
(DOCKET NOS. STN 50-518, -519, -520, -521, -553, -554)

TVA has completed its investigation of items addressed in OIE Bulletin 80-23 and has determined that the subject Valcor solenoid valves having part Nos. V70900-21-1 or 3 are not used at Hartsville or Phipps Bend.

Approximately 10 man-hours were expended in the review of these facilities.