



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

JAN 15 1981

Docket Nos. 50-317  
50-318

Baltimore Gas and Electric Company  
ATTN: Mr. A. E. Lundvall, Jr.  
Vice President, Supply  
P. O. Box 1475  
Baltimore, Maryland 21203

Gentlemen:

Subject: Combined Inspection 50-317/80-16 and 50-318/80-15

This refers to the routine inspection conducted by R. Architzel of this office on October 1 - 31, 1980 at the Calvert Cliffs Nuclear Power Plant, Lusby, Maryland of activities authorized by NRC License Nos. DPR-53 and DPR-69 and to the discussions of our findings held by Mr. Architzel with Mr. L. Russell and others of your staff at the conclusion of the inspection.

Our inspector also verified the steps you have taken to correct the items of noncompliance brought to your attention in letters dated August 27, 1979 and February 13, 1980. We have no further questions regarding your action at this time.

Based on the results of this inspection, it appears that certain of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into the levels as described in our correspondence to you dated December 31, 1974. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved. In addition to the need for corrective action regarding these specific items of noncompliance, we are concerned about the implementation of your management control program that permitted them to occur. Consequently, in your reply, you should describe in particular, those actions taken or planned to improve the effectiveness of your management control program.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosures will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold


8103300 361  
8103300

JAN 15 1981

such information from public disclosure. Any such application must be accompanied by an affidavit executed by the owner of the information, which identifies the document or part sought to be withheld, and which contains a statement of reasons which addresses with specificity the items which will be considered by the Commission as listed in subparagraph (b) (4) of Section 2.790. The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Eldon J. Brunner, Chief  
Reactor Operations and Nuclear  
Support Branch

Enclosures:

1. Appendix A, Notice of Violation
2. Combined Office of Inspection and Enforcement Inspection Report  
Number 317/80-16; 318/80-15

cc w/encl:

- R. M. Douglas, Manager, Quality Assurance
- L. B. Russell, Plant Superintendent
- T. Sydnor, General Supervisor, Operations QA
- R. C. L. Olson, Principal Engineer
- J. A. Tiernan, Manager, Nuclear Power
- R. E. Denton, General Supervisor, Training and Technical Services