



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

10 MAR 1981

Docket No. 99900507/81-01

Sargent & Lundy Engineers  
ATTN: Mr. R. H. Patterson  
Senior Partner  
55 East Monroe Street  
Chicago, Illinois 60603


Gentlemen:

Thank you for your letter of February 26, 1981, in response to our letter dated February 5, 1981. As a result of our review, we find that additional information is needed.

Specifically, in your corrective action response to each identified nonconformance we were unable to determine if Sargent & Lundy had considered the generic implication of each of these nonconformances. Please provide a description of the measures you have taken or plan to take to determine if these were isolated cases or if there were additional cases on the same project and on other projects. Further, we were not able to determine: (1) if the preventive measures described considered the basic causes of these nonconformances so they would not recur, or (2) if you planned to use these preventive measures on other projects. Please re-evaluate your preventive measures in light of the results of your generic considerations of these nonconformances.

Please provide this additional information within 25 days of the date of this letter so we may complete our review in a timely manner.

Sincerely,

  
Uldis Potapovs, Chief  
Vendor Inspection Branch

B105180

445