



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

June 17, 1981



Mr. James G. Keppler, Director
 Directorate of Inspection and
 Enforcement - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2
 Braidwood Station Units 1 and 2
 Supplemental Response to IE Bulletin 80-23
 "Failures of Solenoid Valves Manufactured
 By Valcor Engineering Corporation"
NRC Docket Nos. 50-454/455 and 50-456/457

- References (a): T. J. Rausch letter to J. G. Keppler dated
 February 11, 1981
- (b): T. J. Rausch letter to J. G. Keppler dated
 April 16, 1981

Dear Mr. Keppler:

Commonwealth Edison Company provided in Reference (a) our response to IE Bulletin 80-23 for Byron Units 1 and 2 and Braidwood Units 1 and 2. In that response we indicated our intent to replace certain Valcor solenoid valve coils at these stations and that our schedule was to have replacement completed by April 16, 1981. Subsequently, Reference (b) advised you that our expected replacement completion date would be June, 1981.

This letter is to advise you that the Valcor solenoid valves have been returned to Valcor to have the defective coils replaced. Due to vendor scheduling problems, our expected schedule for coil replacement completion is now October 1, 1981.

Please address any questions you may have concerning this matter to this office.

Very truly yours,

E. Douglas Swartz
 Nuclear Licensing Administrator

cc: Director, Division of
 Reactor Operations Inspection
 2177N

IEH
 5/10

Q
 8106290 326

JUN 18 1981