



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

NSIC



MAY 20 1981

Memorial Community Hospital  
ATTN: Mr. Gordon Butler  
Administrator  
1432 Southwest Boulevard  
Post Office Box 1067  
Jefferson City, Missouri 65101

License No. 24-17680-01  
License No. SNM-1803

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on April 27, 1981, of activities authorized by NRC Byproduct Material Licenses No. 24-17680-01 and Special Nuclear Material License No. SNM-1803 and to the telephone conversation concerning our findings with you on May 6, 1981.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the inspection of License No. SNM-1803; however, during the inspection of License No. 24-17680-01, it was found that certain of your activities appear to be in noncompliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Acting Chief  
Materials Radiation Protection  
Section 1

Enclosure: Appendix A,  
Notice of Violation

cc: Larry P. Courter, M.D.  
Joseph Rackers, R.T.

cc w/encl:  
Central Files  
Reproduction Unit NRC 20b  
PDR  
NSIC

8106240134