

Metropolitan Edison Company Post Office Box 480 Middletown, Pennsylvania 17057 717 Bassandox 948-8000

Waiter's Direct Dial Number

June 16, 1981 LL2-81-0167

Office of Inspection and Enforcement Attn: Boyce H. Grier, Director Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit II (TMI-Operating License No. DPR-73

Docket No. 50-320

Licensee Event Report No. 81-15/IP

This letter is to confirm the conversation between Mr. H. A. McGovern, Unit II Shift Foreman and Mr. T. A. Moslak, Radiation Specialist, TMI Program Office at 0415 hours on June 13, 1981.

A condition considered prompt reportable under Technical Specification 6.9.1.8(f) was entered at 0335 hours on June 13, 1981.

At that time the Control Room Ventilation Monitor, HP-R-220 alarmed due to a temperature inversion. The control room ventilation system failed to automatically switch to the recirculation mode. The control room ventilation was manually shifted to recirculation and the problem investigated. The problem was determined to be in the interlocks key switch was in the defeat position, thus preventing any automatic actions. The reason for the monitor being left in defeat is being investigated.

Further details will be included in the follow-up report,

G. K. Hovey

Director, TMI-2

GKH/MRH/1n

cc: L. H. Barrett, Deputy Program Director

IE22 51/0