

60-328

RECEIVED  
GENERAL SERVICES  
DIVISION

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

December 2, 1980

Mr. James A. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - ANALYSIS OF INTERMEDIATE BREAK LOCATIONS -  
NCR SQN CEB 8027 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
M. Thomas on September 18, 1980, in accordance with 10 CFR 50.55(e). An  
interim report was submitted on October 16, 1980. We expect to submit our  
next report by January 21, 1981.

TVA has not completed the evaluation of possible consequences of postulated  
breaks for the RHR system.

If you have any questions, please get in touch with D. L. Lambert at  
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
5  
1/0