



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

DEC 16 AM 10 38
DISTRIBUTION
SERVICES UNIT
US NRC
OPERATION SERVICES
BRANCH

DEC 08 1980

In Reply Refer To:
RII:TCM
50-327/80-30

Tennessee Valley Authority
Attn: H. G. Parris
Manager of Power
500A Chestnut Street Tower II
Chattanooga, TN 37401

Gentlemen:

Thank you for your letter of October 9, 1980, informing us of steps you have taken to correct the item of noncompliance concerning activities under NRC Operating License No. DPR-77 brought to your attention in our letter of September 17, 1980.

We have reevaluated the noncompliance with 49 CFR 173.392(c)(6) involving bracing of two shipments and find that the items are valid and therefore stand. We have examined your corrective actions in which you state procedures will provide for installation of antiskid blocks at the base of shipping containers where provisions are not built into the transport vehicle and have no further questions at this time.

We appreciate your cooperation with us.

Sincerely,

J. Philip Stohr
J. Philip Stohr, Chief
Fuel Facility and Materials
Safety Branch

- cc: G. G. Stack, Project Manager
- J. M. Ballentine, Plant Superintendent
- J. F. Cox, Supervisor, Nuclear
Licensing Section
- M. J. Burzynski, Project Engineer
- H. N. Culver, Chief, Nuclear Safety
Review Staff

8012190574

Q