

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I				L	Z	I	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5											
7	8	LICENSE CODE										14	LICENSE NUMBER										25	LICENSE TYPE										30	57 CAR 58							

CON'T

REPORT SOURCE: 01 L 6 0 5 0 0 0 2 9 5 7 0 9 2 4 7 9 8 0 1 0 7 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing PT-1 "Rod Cluster Control Exercise" a Rod Urgent Alarm

0 3 | was received while attempting to move Shutdown Bank C. Since the alarm

0 4 | could not be cleared within 2 hours, Unit 1 was brought to hot shutdown

0 5 | within 4 hours per Tech Spec 3.2.2.B.3. The health and safety of the pub-

0 6 | lic was not affected because the rods were capable of being tripped at

0 7 | all times.

08 7 8 9

SYSTEM CODE R B 11		CAUSE CODE E 12		CAUSE SUBCODE G 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE X 15		VALVE SUBCODE Z 16							
EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 9 7 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT A 20		SHUTDOWN METHOD A 21		HOURS 0 0 3 0 22 37 40		ATTACHMENT SUBMITTED N 23 41		NPRD-4 FORM SUB. N 24 42		PRIME COMP. SUPPLIER N 25 43		COMPONENT MANUFACTURER W 1 2 0 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause of the Urgent Alarm was traced to a failure on the pulser/oscillator
1 1 card in the Rod Control Logic cabinet. A spare card was inserted into the
1 2 system and was determined to be defective also. A new card was obtained
1 3 and installed. The system then operated normally. No further corrective
1 4 actions are required.

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 7 7 (29) NA B (31) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 G Z (33) Z (34) NA NA

PERSONNEL EXPOSURES			
NUMBER	TYPE	DESCRIPTION	(39)
17	(37)	21	(38)
NA			

7	8	9	10	11	12	13
PERSONNEL INJURIES						
NUMBER			DESCRIPTION (41)			

1 2 3 4 5 6 7 8 9 10 11 12 NA

LOSS OF OIL DAMAGE TO FACILITY (43)

TYPE		DESCRIPTION
1	9	2
7	8	9
10	11	12
13	14	15
16	17	18
19	20	21
22	23	24
25	26	27
28	29	30
31	32	33
34	35	36
37	38	39
40	41	42
43	44	45
46	47	48
49	50	51
52	53	54
55	56	57
58	59	60
61	62	63
64	65	66
67	68	69
70	71	72
73	74	75
76	77	78
79	80	81
82	83	84
85	86	87
88	89	90
91	92	93
94	95	96
97	98	99
100	101	102
103	104	105
106	107	108
109	110	111
112	113	114
115	116	117
118	119	120
121	122	123
124	125	126
127	128	129
130	131	132
133	134	135
136	137	138
139	140	141
142	143	144
145	146	147
148	149	150
151	152	153
154	155	156
157	158	159
160	161	162
163	164	165
166	167	168
169	170	171
172	173	174
175	176	177
178	179	180
181	182	183
184	185	186
187	188	189
190	191	192
193	194	195
196	197	198
199	200	201
202	203	204
205	206	207
208	209	210
211	212	213
214	215	216
217	218	219
220	221	222
223	224	225
226	227	228
229	230	231
232	233	234
235	236	237
238	239	240
241	242	243
244	245	246
247	248	249
250	251	252
253	254	255
256	257	258
259	260	261
262	263	264
265	266	267
268	269	270
271	272	273
274	275	276
277	278	279
280	281	282
283	284	285
286	287	288
289	290	291
292	293	294
295	296	297
298	299	300
301	302	303
304	305	306
307	308	309
310	311	312
313	314	315
316	317	318
319	320	321
322	323	324
325	326	327
328	329	330
331	332	333
334	335	336
337	338	339
340	341	342
343	344	345
346	347	348
349	350	351
352	353	354
355	356	357
358	359	360
361	362	363
364	365	366
367	368	369
370		

PUBLICITY (4b)
ISSUED (4a) DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARER William D. T'Niemi

PHONE: 312-746-2084 Ext 250