

NOTICE OF VIOLATION

Nuclear Logging Service, Inc.

Docket No. 30-12392
License No. 05-17225-01

As a result of the inspection conducted on May 6, 1981, and in accordance with the attached Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violations were identified:

1. License Condition 2 gives or shows the address for Nuclear Logging Service, Inc., as: 604 W. Kimbark Street
Lafayette, CO 80026

Contrary to this, the licensee has moved to its new location at 4765 Independence Street, Wheat Ridge, Colorado, without notifying NRC of this change.

This is a Severity Level VI violation (Supplement VII.F).

2. License Condition 12 lists the names of 10 individuals specifically authorized to use and/or supervise the use of the licensed materials.

Contrary to this requirement, at least five individuals were using or supervising the use of licensed materials who were not authorized to do so by the license.

This is a Severity Level IV violation (Supplement VII.D.1).

3. 10 CFR 20.203(f) requires, in part, that each container of licensed material shall bear a durable, clearly visible label identifying the radioactive contents, and shall bear the radiation caution symbol and the words "Caution, Radioactive Material."


Contrary to this requirement, a 5mCi Cs-137 calibration source number A731 in the licensee's office facility bore no such identifying or caution labels.

This is a Severity Level V violation (Supplement VII.E).

Pursuant to the provisions of 10 CFR 2.201, Nuclear Logging Service, Inc., is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

Dated _____

MAY 26 1981


Glen D. Brown, Chief
Technical Inspection Branch

8106030 269