Continger Player Company (ACP Pata Maps Stude Play Office Rox 4645 (Conting Georgia 30902 Temptorin 404 522 EMIO

W. A. Widner-

va in Provident and Gereinal Manager Not retic (Winnershop) DEC 80
HANDINGS GEOT



November 26, 1980

U. S. Nuclear Pegulatory Commission Office of Inspection and Enforcement Region II - Suite 3100 101 Marietta Street, NW Atlanta, Georgia 30303

REFERENCE: R!I: JP0 50-321 50-366 TAE Bulletin 80-21

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

In response to I&E Bulletin 80-21, "Valve Yokes Supplied by Malcolm Foundry Company, Inc.", a determination has been made that no valve yokes supplied by Malcolm Foundry Company, Inc. are in use or have been purchased for Plant E. I. Hatch.

A search through the equipment location index and foreign drawings indicates that several Anchor Darling valves are in use in safety-related systems. Valve documentation on site indicates that foundries, other than Malcolm, made the valve yokes found at Plant Hatch.

If any additional information is desired, please contact this office.

Very truly yours,

W. A. Widner

DLT/mb

xc: Director of the Office of Inspection and Enforcement Director of the Division of Operating Reactors, Office of Nuclear Reactor Regulation