NRC FORM 591M PA	RT 1		U.S. NU	CLEAR REGULATOR		COMMISSION			
(07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATION INSPECTED: 2. NRC/REGIONAL OFFICE									
	16 ed: Huntington, WV		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(S									
3. DOCKET NUMBER(S)		4. LICENSE NUMBER	NUMBER(S) 5. DATE(S) OF INSPE 10/09/19, with it 10/09/19, with it						
030-38194		41-25460-01		review through 1	2				
Regulatory Commissi procedures and repre- 1. Based on 2. Previous 3. The violat non-repet	n examination of the activities conduct ion (NRC) rules and regulations and the esentative records, interviews with pers the inspection findings, no violations w violation(s) closed. ions(s), specifically described to you by itive, and corrective action was or is be , were satisfied. Non-cited violation(s) were discuss	e conditions of your onnel, and observat vere identified. y the inspector as no ing taken, and the r	license. The inspection consist tions by the inspector. The inspe on-cited violations, are not being emaining criteria in the NRC En	ed of selective examin ection findings are as cited because they w	er	ions of lows: e self-identified, :			
cited in ac with 10 C	s inspection, certain of your activities, a coordance with NRC Enforcement Polic FR 19.11. s and Corrective Actions)								
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps wh date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically									
TITLE	PRINTED NAME	-	SIGNATURE			DATE			
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR	Todd Jackson (Region I)		P.4- Cr44	rej (for TJ		12/06/2019			
BRANCH CHIEF	Robert Ruiz, Acting Chief		Raver P	•		14/11/19			

NRC FORM 591M PART 3 (07-2012) 10 CFR 2.201 U.S. NUCLEAR REGULATOR Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATION INSPECTE S&ME, Inc. 2724 Discovery Drive Raleigh, NC 27616 Location Inspected: Hunti REPORT NUMBER(S) 201900	ngton, WV		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
3. DOCKET NUMBER(S) 030-38194		4. LICENSE NUMBER(S) 41-25460-01		5. DATE(S) OF INSPEC 10/09/19, with in review through 1	office				
6. INSPECTION PROCEDURES USE 87124	ED	7. INSPECTION FOCUS AREAS All							
SUPPLEMENTAL INSPECTION INFORMATION									
1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT4. TELEPHONE NUMBRonald Juliani - Corporate RSO(919) 63							
Main Office Inspection Next Inspection Date: No Change ✓ Field Office Inspection 110 12th Street West, Huntington, WV Temporary Job Site Inspection									
PROGRAM SCOPE									

This was an unannounced field inspection of a geotechnical engineering company authorized to store portable moisture density gauges at field offices in New Albany, Indiana and Huntington, West Virginia, and to use them at temporary job sites in NRC jurisdiction. The scope of this inspection was limited to observations at the licensee's field office in Huntington. At the time of the inspection, no gauges had yet been stored or dispatched from this location, hor were there any temporary job sites currently in the state. The site RSO from the Lexington, KY office maintained day-to-day oversight of both authorized locations for the Corporate RSO, who was based in Raliegh, NC and who visited each authorized location at least annually.

PERFORMANCE OBSERVATIONS

The inspector toured the facility in Huntington, which the licensee had recently begun remodeling in anticipation of future gauge storage. The storage room within the building was under construction in accordance with the floor plan provided to the NRC in its January 7, 2019 renewal application. The storage room appeared to be adequately designed for secure storage of gauges, with no window or ceiling access and a door which was prepared to have two locking mechanisms installed. The inspector interviewed an authorized user from the Lexington, KY office with respect to planned gauge use. No records were maintained at the location, and no postings were yet in-place or necessary.

Following the inspection, a Region III inspector contacted the Corporate RSO to discuss the status and oversight of the licensee's radiation safety program as implemented in NRC jurisdiction. The inspector noted that the licensee also currently dispatched licensed material on occasion from its Louisville, TN office to a job site at a federal facility (Y-12) in Oak Ridge, TN.

No violations of NRC requirements were identified as a result of this inspection.