



DISTRIBUTION  
SERVICES UNIT

ARKANSAS POWER & LIGHT COMPANY

1980 NOV 20 AM 10 54 POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

November 13, 1980

U.S. NRC  
DISTRIBUTION SERVICES  
BRANCH

2-110-21

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report No. 80-079/03L-0  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning the inoperable conditions of the "C" High Pressure Safety Injection Pump (HPSI) during Mode 1 operation.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:GAC:lp

*801*  
Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

801 121 0595



MEMBER MIDDLE SOUTH UTILITIES SYSTEM