



71C

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

November 26, 1980

Docket No. 50-267/80-22

RECEIVED
GENERAL INVESTIGATIVE
DIVISION
NOV 27 1980
1980 DEC 2 PM 1 16
COMMUNICATIONS SECTION

Public Service Company of Colorado
ATTN: Mr. C. K. Millen
Senior Vice-President
Post Office Box 840
Denver, Colorado 80201

Gentlemen:

This letter refers to the October 20-24, 1980 routine inspection conducted by Mr. R. A. Caldwell of NRC's Region IV Office. The activities inspected were those that are authorized under NRC License No. DPR-34. It further refers to the discussion that he had with your staff concerning his findings at the conclusion of the inspection.

The inspection related to your program and activities designed to protect against industrial sabotage and to safeguard special nuclear material. The inspection was based on the applicable provisions of Title 10, Part 50, of the Code of Federal Regulations, entitled, "Licensing of Production and Utilization Facilities," within Part 73 entitled, "Physical Protection of Plants and Materials," and the specific requirements of NRC License No. DPR-34. The inspection consisted of selective examinations of procedures and records, personnel interviews, and observations by the inspector.

No items of noncompliance with NRC requirements, within the scope of this inspection, were identified.

The documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility's security procedures are exempt from disclosure. This exemption is covered within Title 10 CFR, Part 2, Section 2.790(d), entitled, "Rules of Practice for Domestic Licensing


9

8012110 780

November 26, 1980

Proceedings." Therefore, the inspection report will not be placed in the Public Document Room and distribution will be limited. If you have any questions concerning this report, we will be pleased to discuss them with you.

Sincerely,



James A. F. Kelly
Chief, Physical Security Branch

Enclosure:

IE Inspection Report No. 50-267/80-22

cc: Mr. Don Warembourg
Manager, Nuclear Production
P. O. Box 361
Platteville, Colorado, 80651