

James W Cook Vice President - Projects, Engineering and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0453

December 30, 1980

Mr J G Keppler, Regional Director Office of Inspection & Enforcement US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT
UNIT NO 1, DOCKET NO 50-329
UNIT NO 2, DOCKET NO 50-330
LETDOWN COOLER SUPPORTS
FILE: 0.4.9.38 UFI: 73*10*01, 15240(E), 02312(S) SERIAL: 10994

Reference: CPCo Letters to J G Keppler, Same Subject:

- 1) Serial Howe-64-80, dated March 27, 1980
- 2) Serial 9180, dated June 19, 1980
- 3) Serial 9769, dated October 10, 1980

This letter, as were the referenced letters, is an interim 50.55(e) report concerning the overstressed condition in letdown cooler supports.

The manufacturer and B&W are still in the process of analyzing the letdown cooler supports based on the actual nozzle loads supplied by the Architect/Engineer. The result of the analyses were expected to be available by December. Once these loads are available, the Architect/Engineer will analyze the existing support to determine the extent of the modification required.

Another report, either interim or final, will be sent on or before January 30, 1981.

JTW/1r

CC: Director, Office of Inspection & Enforcement Att Mr Victor Stello, USNRC (15)

teclar For Two Cook

Director, Office of Management Information & Program Control, USNRC (1) B019

1/1

CC: RJCook, NRC Resident Inspector Midland Nuclear Plant (1)

CBechhoefer, ASLB Panel
GALinenberger, ASLB Panel
FPCowan, ASLB Panel
AS&L Appeal Panel
MMCherry, Esq
MSinclair
CRStephens, USNRC
WDPaton, Esq, USNRC
FJKelly, Esq, Attorney General
SHFreeman, Esq, Asst Attorney General
GTTaylor, Esq, Asst Attorney General
WHMarshall
GJMerritt, Esq, TNK&J