



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

November 14, 1980

CENTRAL FILES  
PDR:HQ  
LPDR  
~~TIC~~  
NSIC  
STATE

In Reply Refer To:  
Docket No. 50-298/80-16

Nebraska Public Power District  
ATTN: Mr. J. M. Pilant, Director  
Licensing and Quality Assurance  
P. O. Box 499  
Columbus, Nebraska 68601

Gentlemen:

This refers to the inspection conducted by Mr. R. G. Spangler of this office during the period of October 21-24 and 29-31, 1980, of activities authorized by NRC Operating License DPR-46, and to the discussions of the findings with Mr. L. C. Lessor.

Areas examined during the inspection and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office within twenty (20) days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

8101 100029

Nebraska Public Power District

2

November 14, 1980

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



G. L. Madsen, Chief  
Reactor Operations and  
Nuclear Support Branch

Enclosure:  
Inspection Report No. 50-298/80-16

cc w/enclosure  
L. C. Lessor, Superintendent  
Cooper Nuclear Station  
P. O. Box 98  
Brownville, Nebraska 68321