

DEC 28 1980

DEC 15 11 9 13
NRC
REGISTRATION

Docket No. 50-213

REGULATORY ROCKET FILE COPY

Mr. W. G. Council Vice President
Nuclear Engineering and Operations
Connecticut Yankee Atomic Power Co.
Post Office Box 270
Hartford, Connecticut 06101

Dear Mr. Council:

SUBJECT: HADDAM NECK - SEP TOPIC III-3.B, STRUCTURAL AND OTHER
CONSEQUENCES (E.G. FLOODING OF SAFETY RELATED EQUIPMENT
IN BASEMENTS) OF FAILURE OF UNDERDRAIN SYSTEMS

This letter is to advise you that Topic III-3.B, "Structural and Other
Consequences (e.g. Flooding of Safety Related Equipment in Basements)
of Failure of Underdrain Systems" is applicable to your facility and
supersedes our letter of November 16, 1979 to you.

The reason for this change is the identification of a mat sump beneath
the containment building.

Sincerely,

Paul O'Connor for

Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Licensing

cc: See next page

DISTRIBUTION:

| | | |
|-----------------|-----------|---------|
| Docket | HSmith | GStaley |
| NRC PDR | RCaruso | |
| Local PDR | GCwalina | |
| TERA | DPersinko | |
| NSIC, JBuchanan | RHermann | |
| JHeltemes, AEOD | SEP File | |
| OELD | DEisenhut | |
| I&E (3) | RPurple | |
| ACRS (16) | JRoe | |
| NRR Reading | RTedesco | |
| SEPB Reading | TNovak | |
| WRussell | GLainas | |
| DCrutchfield | JWetmore | |

PROG DMC

| | | | | | | |
|---------|--------------|-----------|-----------|-------------|--------------|----------|
| OFFICE | SEPB:DL | SEPB:DLSL | SEPB:DL:C | ORB#5:DL:PM | ORB#5:DL:C | AD:SA:DL |
| SURNAME | DPersinko:dk | RHermann | WRussell | RCaruso | DCrutchfield | GLainas |
| DATE | 12/16/80 | 12/16/80 | 12/16/80 | 12/15/80 | 12/15/80 | 12/ /80 |

8101190 685 P



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

DEC 26 1990

Docket No. 50-213
LS05-80-12-059

Mr. W. G. Council, Vice President
Nuclear Engineering and Operations
Connecticut Yankee Atomic Power Co.
Post Office Box 270
Hartford, Connecticut 06101

Dear Mr. Council:

SUBJECT: HADDAM NECK - SEP TOPIC III-3.B, STRUCTURAL AND OTHER
CONSEQUENCES (E.G. FLOODING OF SAFETY RELATED EQUIPMENT
IN BASEMENTS) OF FAILURE OF UNDERDRAIN SYSTEMS

This letter is to advise you that Topic III-3.B, "Structural and Other Consequences (e.g. Flooding of Safety Related Equipment in Basements) of Failure of Underdrain Systems" is applicable to your facility and supersedes our letter of November 16, 1979 to you.

The reason for this change is the identification of a mat sump beneath the containment building.

Sincerely,

Paul W. Connor for D.M.C.

Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Licensing

cc: See next page

Mr. W. G. Council

HADDAM NECK PLANT
DOCKET NO. 50-213

cc

Day, Berry & Howard
Counselors at Law
One Constitution Plaza
Hartford, Connecticut 06103

Superintendent
Haddam Neck Plant
RFD #1
Post Office Box 127E
East Hampton, Connecticut 06424

Mr. James R. Himmelwright
Northeast Utilities Service Company
P. O. Box 270
Hartford, Connecticut 06107

Russell Library
119 Broad Street
Middletown, Connecticut 06457

Board of Selectmen
Town Hall
Haddam, Connecticut 06103

Connecticut Energy Agency
ATTN: Assistant Director
Research and Policy
Development
Department of Planning and
Energy Policy
20 Grand Street
Hartford, Connecticut 06106

Director, Technical Assessment
Division
Office of Radiation Programs
(AW-459)
U. S. Environmental Protection
Agency
Crystal Mall #2
Arlington, Virginia 20460

U. S. Environmental Protection
Agency
Region I Office
ATTN: EIS COORDINATOR
JFK Federal Building
Boston, Massachusetts 02203

Resident Inspector
Haddam Neck Nuclear Power Station
c/o U. S. NRC
East Haddam Post Office
East Haddam, Connecticut 06423