

Westinghouse
Electric Corporation

Water Reactor
Divisions

Nuclear Technology Division

Box 355
Pittsburgh Pennsylvania 15230

December 10, 1980

NS-TMA-2356

Mr. Norman G. Moseley
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
East West Towers Building
4350 East West Highway
Bethesda, Maryland 20014



Dear Mr. Moseley:

Enclosed are twenty (20) copies of WCAP-9812, "Investigation of Feedwater Line Cracking in Pressurized Water Reactor Plants," June 1980. This is the Non-Proprietary version of the Proprietary version (WCAP-9693) as provided by letter NS-TMA-2327, November 10, 1980.

Both report versions were prepared and are submitted to Staff at the request of the Feed Line Cracking Owners Group. The information contained is only applicable to members of the Feed Line Cracking Owners Group.

We trust that this closes the commitment expressed in the November 10, 1980 letter, NS-TMA-2327, for providing the Non-Proprietary version.

Very truly yours,

A handwritten signature in cursive script, appearing to read "T. M. Anderson".

T. M. Anderson, Manager
Nuclear Safety Department

RDB/bek
Enclosures

8101200420

B