

January 21, 1981

In reply, please
refer to LAC-7346

DOCKET NO. 50-409

Director of Nuclear Reactor Regulation
ATTN: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
GROUTING OF VOIDS UNDER TURBINE BUILDING MAT

REFERENCES: (1) NRC Letter, Crutchfield to Linder,
dated July 28, 1980.
(2) DPC Letter LAC-7100, Linder to Crutchfield,
dated August 25, 1980.
(3) DPC Letter LAC-7131, Linder to Crutchfield,
dated September 9, 1980.
(4) DPC Letter LAC-7253, Linder to Crutchfield,
dated November 26, 1980.

Gentlemen:

Our recent submittal (Reference 4) contained information regarding
the injection of grout into voids under the Turbine Building mat.

The second paragraph of Reference (4) describes the basic grout mix
and states that one of the materials used was:

"Type I Portland Cement-----2 bags @ 49 pounds each."

Please revise this line to read as follows:

"Type I Portland Cement-----2 bags @ 94 pounds each."

Should you have any questions regarding this submittal, please
contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder

Frank Linder, General Manager

FL:FAD:abs

CC: J. Keppler, Reg. Dir., NRC-DRO III
NRC Resident Inspectors

POOR ORIGINAL

P 8101270 345