Appendix A

NOTICE OF VIOLATION

Consumers Power Company

Docket No. 50-155

Based on the inspection of May 22-26, 1978, it appears that a certain activity was in noncompliance with NRC requirements, as noted below. This item is an infraction.

Peactor Depressurization System was placed in the degraded condition when the fire pump control switches were placed in the "INHIBIT" position during maintenance activities.