

TIC

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

JAN 9 8:40  
January 5, 1981

TELEPHONE: AREA 704  
373-4083

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Re: RII: JPO  
McGuire Nuclear Station  
Docket No. 50-369 and 50-370



Dear Mr. O'Reilly:

In response to your letter of November 6, 1980 which transmitted IE Bulletin 80-21, we wish to advise that a review of McGuire Nuclear Station valve yolks has been conducted.

We have received a response from all but one of our valve manufacturers. At this time no valves have been identified as having parts cast by Malcolm Foundry Company, Inc. We will notify you if the last manufacturer identifies potentially faulty material.

Very truly yours,

*William O. Parker Jr.*  
William O. Parker, Jr.

RWO:njs

cc: U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
Division of Reactor Construction Inspection  
Washington, D. C. 20555

810 1290404 Q