

Thomas J. Martin
Vice President
Engineering and Construction

Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/430-8316

October 14, 1980

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

NRC INSPECTION REPORT NO. 50-354/79-04
NO. 1 UNIT
HOPE CREEK GENERATING STATION


The following is a supplemental response to NRC Inspection Report No. 50-354/79-04. It is in reply to NRC letter of August 21, 1980 concerning the subject of I.D. weld build-ups. We have evaluated the NRC concern and accept the position taken.

An evaluation of all weld buildups is being conducted in order to determine the corrective measures required. Hence the date (September 30, 1980) previously projected for full compliance of corrective action concerning the subject inspection is to be revised pending the results of the re-evaluation.

PSE&G anticipates a response will be transmitted by December 12, 1980 addressing those corrective action measures taken.

If you require additional information, we will be pleased to discuss it with you.

Very truly yours,



CC Office of Inspection & Enforcement
Div. of Reactor Construction & Inspection
Washington, DC

H. E. Morris
Bechtel Power Corporation
San Francisco, CA

8101290781