



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (F.O.) 371-4000

January 20, 1981

2-011-21

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



SUBJECT: Arkansas Nuclear One-Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report No. 80-087/03 X-1
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9.b., attached is the subject report concerning the failure of the High Pressure Safety Injection Valve (2CV-5056) during Mode 2 operation. This is an update to a previous report submitted December 26, 1980.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:GAC:st
80y
Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

*A002
S.I.I*

8102100 125

MEMBER MIDDLE SOUTH UTILITIES SYSTEM