

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | T | M | N | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

REPORT SOURCE 7 8 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER 0 1 5 0 0 0 0 3 3 6 7 0 1 0 6 8 1 1

EVENT DATE 0 1 1 3 0 8 1 1

REPORT DATE 0 1 1 3 0 8 1 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During a routine inspection, main steam line snubber 413019 was found with no visible

03 | fluid level. At the time of the discovery the plant was in a cold shutdown condition.

04 | The snubber is an ITT Grinnell, FIG. 200, 4 inch bore by 5 inch stroke unit.

05 | Similiar LER's 77-47, 79-28, 80-12

0	6	
---	---	--

0	7	
---	---	--

0	8		8
7	8		

0 9 7 8

H B 9 10 11

B 11 12

C 12 13

S U P P O R T 13 14 18

D 15 19

Z 16 20

LER/RO REPORT NUMBER	EVENT YEAR	REPORT NO.	CODE	TYPE	NO.
17	811	0003	03	1	0
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED
18	19	20	21	22	23
0	0	0	0	0	N
PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER				
24	25				
Y	A				
26	27				
0	0				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The plastic fluid reservoir deformed due to overheating when insulating pads were

111 installed over a portion of the snubber after relocation of the hanger and snubber

1 2 during a recent outage. The defective snubber was replaced. An inspection was per-

13 | formed verifying additional hanger-work has not caused similar occurrences.

1	d	
---	---	--

8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 G (28) 0 0 0 (29) NA B (31) OPERATOR OBSERVATION

10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 7 33 7 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES			
NUMBER		TYPE	DESCRIPTION
1	7	37	38 NA

PERSONNEL INJURIES		DESCRIPTION
NUMBER		
1	8	NA

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY																							
TYPE		DESCRIPTION																					
1	9	7	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22

	PUBLICITY	(45)	NARC USE ONLY
ISSUED	DESCRIPTION		
2 0	NA		
7	8	9	10
68	69		80

NRC USE ONLY

8102100598

John G. Resetar Jr.

203-447-1791