U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

Report No.	50-293/80-31		TV
Docket No.	50-293 License No. DPR-35	Safeguards	Group C
Licensee:	Boston Edison Company M/C Nuclear		
	800 Boylston Street		
	Boston, Massachusetts 02199		
Facility Na	me: Pilgrim Nuclear Power Station		
Inspection	At: Plymouth, Massachusetts		
Inspection	Conducted: November 10-14, 1980		
Date of Las	st Physical Security Inspection : Jun	e 3, 1980	
Type of Ins	spection: Routine, Unannounced Physical Secu	rity	
Inspectors:	Milliam Madden, Physical Security/Inspect	or	Duc 9.1980
			date
			date
Approved by	y: Edward Women jo Jo J. W. Deviller, Chief, Security Section Safeguards Branch		Dulo 1980
Inspection	Summary: Inspection on November 10-14, 1980	(Report No	50-293/80-31)

Areas Inspected: Included review of Security Plan; Security Organization; Physical Barriers (Protected Area); Physical Barriers (Vital Areas); Lighting; Access Control (Identification, Authorization, and Badging); Access Control (Search); Access Control (Escorting); Access Control (Vital Areas); Alarm Stations; Detection Aids; Communications; Testing and Maintenance; Compensatory Measures; Power Supply; Response; Locks, Keys and Combinations and Records and Reports.

The inspection involved 38.5 inspector-hours onsite by one NRC inspector. The inspection began during regular hours; 5 Inspector-hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements in 17 of the 18 functional areas examined. One item of noncompliance was identified as follows:

1. Physical Barriers (Vital Areas) - Failure to maintain a Vital Area door in a locked mode. (Infraction, Paragraph 7)

Region I Form 167 (August 1979)

8102720497