

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 3 2 0 0 7 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32

CON'T
0 1 REPORT SOURCE L 5 0 5 0 0 0 2 4 9 7 0 1 2 0 8 1 3 0 2 1 3 8 1 9
7 8 9 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation while performing isolation condenser condensate line hi-flow
0 3 calibration, dPIS 3-1349B tripped at 34 inches water column differential pressure.
0 4 Tech. Spec. Table 3.2.1 limit is less than or equal to 32 inches of water
0 5 column. Safety significance is minimal because redundant switch would have provided
0 6 isolation within Tech. Spec limit. Similar events: 76-26/03L-0, 79-22/03L-0,
0 7 79-58/03L-0, 80-11/03L-0 and 80-25/03L-0.

0 8 _____

0 9 SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE S 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16

17 LER/RO REPORT NUMBER 3 1 21 22 EVENT YEAR 3 1 23 24 SEQUENTIAL REPORT NO. 0 0 3 25 26 OCCURRENCE CODE 0 3 27 28 REPORT TYPE L 29 30 REVISION NO. 0 31 32
ACTION TAKEN E 18 33 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 35 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 22 37 ATTACHMENT SUBMITTED N 23 40 NPD-4 FORM SUB. Y 24 42 PRIME COMP. SUPPLIER N 25 43 COMPONENT MANUFACTURER B O 8 0 26 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for the setpoint drift is unknown. The Barton Model 288 indicating switch
1 1 was readjusted to trip at 29 inches water column differential pressure increasing
1 2 and repeatability was verified. DIS 1300-2 will continue to be performed monthly
1 3 to verify setpoint.

1 4 _____

1 5 FACILITY STATUS E 28 29 % POWER 0 9 7 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 32 DISCOVERY DESCRIPTION Routine Surveillance Testing 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 ACTIVITY CONTENT Z 33 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUED N 44 45 DESCRIPTION N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER Raymond Magrow PHONE: (815)942-2920 X 421
NRC USE ONLY