


Docket No. 50-346

License No. NPF-3

Serial No. 1-189

March 6, 1981



RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221


James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter is in response to IE Bulletin No. 81-01, dated January 27, 1981 and applicable to Davis-Besse Nuclear Power Station Unit 1.

No INC mechanical snubbers are installed at Davis-Besse Unit 1, therefore, items 1 and 2 under "Actions to be Taken by Licensees of Operating Reactors" are not applicable to Davis-Besse 1. Item 3 requested a schedule for an inspection program covering mechanical snubbers produced by other manufacturers. The required inspection program will be completed for Davis-Besse 1 prior to the completion of the next refueling outage (currently scheduled for March, 1982). As requested in item 4, the results of the inspection will be submitted within 60 days after the completion of the inspection.

Very truly yours,



RPC/JKW

cc:

Director of the NRC Office of Inspection and Enforcement
Washington, D. C. 20555
DB-1 NRC Resident Inspector

bt c/6

