



VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET
RUTLAND, VERMONT 05701

2.C.2.9
REPLY TO: FVY 81-37
ENGINEERING OFFICE
1671 WORCESTER ROAD
FRAMINGHAM, MASSACHUSETTS 01701
TELEPHONE 617-872-8100

March 4, 1981

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Mr. Boyce H. Grier, Director

References: (a) License No. DPR-28 (Docket No. 50-271)
(b) Letter, USNRC to VYNPC dated May 8, 1980;
IE Bulletin 80-11
(c) Letter, VYNPC to USNRC dated July 7, 1980
(d) Letter, VYNPC to USNRC (WVY 80-157) dated
November 10, 1980
(e) Letter, VYNPC to USNRC (WVY 80-126) dated
September 4, 1980

Subject: Response to IE Bulletin 80-11

Dear Sir:

In accordance with the requirements contained in Reference (b) and our commitment as documented in Reference (e), we have completed our re-evaluation of block walls at Vermont Yankee. This re-evaluation was performed in accordance with the criteria outlined in Reference (d). All modifications to block walls shown to be necessary through this effort will be completed by the end of the 1981 refueling outage.

The following information is submitted as an estimate of the manpower expended in the research and response for this Bulletin:

<u>Manpower Activity</u>	<u>Manhours Expended</u>
Research and Response	
Preparation	380
Corrective Actions	5480

Vermont Yankee believes that the information given above,

8104080 772

9



