

APPENDIX A  
NOTICE OF VIOLATION

Alabama Power Company  
Farley 1

Docket No. 50-348  
License No. NPF-2

As a result of the inspection conducted on January 12-16, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

Technical Specification 6.8.1 requires written procedures shall be established, implemented and maintained. FNP-0-AP-6, Procedure Adherence, Revision 1, dated 4/77 requires that deviations from plant procedures be documented and approved by appropriate plant personnel.

Contrary to the above, written procedures were not being maintained. FNP-1-SOP-23.0, Component Cooling Water System, Revision 2 dated 11/79, required the position of valve Q1P17V189 RHR pump 1A seal Hx CCW inlet line drain to be open (it should be closed for normal system operation). The most recent valve lineup of the CCW system identified that the valve was in the closed position and the valve lineup had a correction written into the required valve position column. No temporary change notice or other documentation was initiated as required by FNP-0-AP-6, Procedure Adherence.

This is a Severity Level V Violation (Supplement I.E.).

Pursuant to the provisions of 10 CFR 2.201, Alabama Power Company is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date: FEB 11 1981

8104060 127