



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

March 12, 1981

In Reply Refer To:
Docket No. 50-267/81-02



Public Service Company of Colorado
ATTN: Mr. C. K. Millen
Senior Vice President
P. O. Box 840
Denver, Colorado 80201

Gentlemen:

This refers to the inspection conducted by Messrs. J. R. Boardman and J. P. Jaudon of this office during the period January 26-30, 1981, of activities authorized by NRC Operating License No. DPR-34 and to their discussions of the findings with members of your staff at the conclusion of the inspection.

Areas examined during the inspection and the findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

During this inspection it was found that certain of your activities were not conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter, in writing in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.


In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office within 25 days of the date of this letter, requesting that such information be withheld from public disclosure. This application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

8104280 679

March 12, 1981

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



G. L. Madsen, Chief
Reactor Projects Branch

Enclosures:

1. Notice of Violation
2. IE Inspection Report No. 50-267/81-02

cc w/enclosures:

D. W. Warembourg, Nuclear Production Manager
Fort St. Vrain Nuclear Station
P. O. Box 368
Platteville, Colorado 80601

L. Brey, Quality Assurance