MU

THE COMPACTION IS SHAD PROVIDED CONTANY THE SEARCH CHAPTERS SHAD CONTANY AND THE CONTANY AND THE CONTANY AND THE SEARCH CHAPTERS SHAD CONTANY AND AND ASSESSED THE SEARCH CHAPTERS AND ASSESSED ASSESSED.

P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

April 30, 1981

MP-2-4676

Mr. Boyce H. Grier
Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/81-16/3L-0

Dear Mr. Grier:

This letter forwards Licensee Event Report 81-16/3L-0 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition for operation. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

Station Superintendent
Millstone Nuclear Power Station

EJM/RWB:mw

Attachment: LER 81-16/3L-0

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30)

Director, Office of Management Information and Program Control, Washington, D.C. (3)

U. S. Nuclear Regulatory Commission, c/o Document Management Branch, Washington, D.C. 20555