ILLINOIS POWER COMPANY



U-0224 L08-81(04-06)-6 500 SOUTH 27TH STREET, DECATUR, ILLINOIS 62525 April 6, 1981

Mr. James G. Keppler Director, Region III Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Clinton Power Station Units 1 & 2
Docket Nos. 50-461 and 50-462
Construction Permits No. CPPR-137 & CPPR-138

This is in reply to your letter of November 6, 1980, whereby you forwarded IE Bulletin No. 80-21 which reported on the failures of some valve yokes supplied by Malcolm Foundry Co., Inc.

Please be advised that Clinton Unit 1 has no active safety related valves with parts cast by Malcolm Foundry Co., Inc.

Sincerely,

G. E. Wuller

Supervisor - Licensing Nuclear Station Engineering

GEW/em

cc: H. H. Livermore, NRC Resident Inspector
Director, Office of I & E, Div. of Reactor Operations Inspection
NRC, Washington, D. C.