



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 5, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Inoperability of No. 22 Turbine-Driven
Auxiliary Feedwater Pump

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2 (b), since it represents operation on a degraded mode permitted by a limiting condition for operation.

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

B105080 283