Edison comme

PILORIM NUCLEAR POWER STATION RFD #1 ROCKY HILL RGLO PLYMOUTH: MASSACHUSETTS 02360

R. D. MACHEN
ASSELLA SPERATORA MANAGEA
A LAR M SPEREN

Director, Region 1
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406
Licensee Event Report 81-014/03L-0

May 14, 1981

BECO Ltr. #81-113

MAY 2 7 1981

MAY 2 7 1981

WAS NUCLEAR REGULATORY
COMMISSION

Docket Number 50-293 License DPR-35

Gentlemen:

The attached Licensee Event Report 81-014/03L-0, entitled "LPCI Instrument DPIS 261-3°B", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

This report has been delayed several days because management controls required re-analysis of the root cause of this event to ensure adequate and effective corrective action is initiated and reported.

Respectfully submitted,

R. D. Machon

Nuclear Operations Manager

Pilgrim Station

MIM:ep

Enclosures: (3 copies) LER 81-014/03L-0

cc: Director (40 copies)
 Office of Management Information and Program Control
 U. S. Nuclear Regulatory Commission
 Washington, D.C. 20555