



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 22 1981

Docket No. 50-186

University of Missouri
ATTN: Dr. Robert M. Brugger
Director
Research Reactor
Facility
Research Park
Columbia, MO 65201

Gentlemen:

This refers to the routine safeguards inspection conducted by Ms. G. M. Christoffer of this office on May 5-6, 1981, of activities at the University of Missouri (Columbia) Research Reactor authorized by NRC License No. R-103 and to the discussion of our findings with members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the Public Document Room.

8106010333

Q
ATTACHMENT CONTAINS
PART 2.790(d) INFORMATION

1E02
5/11

MAY 22 1981

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

C. E. Norelius, Acting Director
Division of Engineering and Technical
Inspection

Enclosure: IE Inspection
Report No. 50-186/81-02
(Part 2.790(d) Information)

cc w/encl:
Central Files
Reproduction Unit NRC 20b

cc w/encl w/o Part 2.790(d)
Information:
PDR
NSIC
TIC

RIII
[Signature]
for Christoffer/so
5/18/81

RIII
[Signature]
for Creed

RIII
[Signature]
for Fisher

RIII
[Signature]
for Ridgway

RIII
[Signature]
for Norelius

ATTACHMENT CONTAINS
PART 2.790(d) INFORMATION