



Portland General Electric Company
 Trojan Nuclear Plant
 P.O. Box 459
 Astoria, Oregon 97103
 (503) 326-3713

May 18, 1981
 CPY-394-81

Mr. R. H. Engelken, Director
 Nuclear Regulatory Commission, Region V
 1990 North California Blvd.
 Walnut Creek, CA 94596



Dear Sir:

In accordance with the Trojan Plant Operating License, Appendix A, US NRC Technical Specifications, Paragraph 6.9.1.7, attached is Licensee Event Report No. 81-08, concerning a situation where the Technical Specification for containment isolation valves was not satisfied due to an inoperable valve.

Sincerely,

CP Baird
 C. P. Yundt
 General Manager

CP
 CPY/RPS:na
 Attachments

c: LER Distribution



*Assoc
 S.I.*

810600 1451

S

81-116

9. Corrective Action:

All water damage to the operator was repaired and the motor was replaced. The circuit was checked and the valve was successfully tested and returned to operation. Further overhaul of the operator will be done during the 1981 Refueling Outage.

An engineering evaluation will be made to determine if the location of the valve should be changed.

Administrative controls have been established to prevent flooding of the of the containment recirculation sump in the future.