

(412) 460-6000

DUQUESNE LIGHT COMPANY Beaver Valley Power Station Post Office Box 4 Shippingport, PA 15077

May 29, 1981 BVPS:JAW:1190

Beaver Valley Power Station, Unit No. 1 Docket No. 50-334, License No. DPR-66 LER 81-046/01P

Mr. B. H. Grier, Director of Regulation United States Nuclear Regulatory Commission Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

In accordance with Environmental Technical Specification 2.4.4.2, the following occurrence is reported. The report was discussed with our Resident Inspector; Mr. D. A. Beckman, at approximately 1400 hours on May 29, 1981.

During routine review of Radcon surveillance records for the period of May 27 through May 29, 1981, it was discovered that a sample of the gaseous waste discharge path was not taken on May 28, as required with the radiation monitor, [RM-GW-108A, B], out of service. The required samples were taken on May 27 and 29.

The health and safety of the general public was not jeopardized since no gaseous waste releases occurred during the period. Any additional information or corrective action will be included in the follow-up report.

Very truly yours,

for J. A. Werling Superintendent

Superintendent

1/1

Mr. B. H. Grier May 29, 1981 BVPS:JAW:1190 Page 2

cc: Director Of Management & Program Analysis
United States Notlear Regulatory Commission
Washington, D. C. 20555

Director, Office of Inspection and Enforcement Headquarters United States Nuclear Regulatory Commission Washington, D. C. 20555

- D. A. Chaney, BVPS Licensing Project Manager United States Nuclear Regulatory Commission Washington, D. C. 20555
- D. A. Beckman, Nuclear Regulatory Commission, BVPS Site Inspector Mr. Alex Timme, CAPCO Nuclear Projects Coordinator, Toledo Edison Nuclear Safety Analysis Center, Palo Alto, California
- G. E. Muckle, Factory Mutual Engineering, Pittsburgh
- R. C. Wittschen, Stone & Webster/Boston