

YANKEE ATOMIC ELECTRIC COMPANY

Telephone 617 872-8100



1671 Worcester Road, Framingham, Massachusetts 01701

2.C.2.9

FYR 81-77

May 8, 1981

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Boyce H. Grier, Director
Region I
Office of Inspection and Enforcement

References: (a) License No. DPR-3 (Docket No. 50-29)
(b) USNRC Letter to YAEC dated April 9, 1981

Subject: Response to IE Bulletin 81-02, "Failure of Gate Type Valves to
Close Against Differential Pressure"

Dear Sir:

This letter is to inform you that none of the affected valves described in Reference (b) are installed or maintained as spares for installation at Yankee Rowe; and therefore no further action is necessary.

If you have any further questions, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

E. Jackson for
D. E. Moody
Manager of Operations

JAK/kab



8106040 462

Q