
YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

June 1, 1981

Mr. B. H. Grier, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Licensee Event Report 50-29/81-05/03L

Failure of #17 Control Rod to Scram

Dear Mr. Grier:

In accordance with Technical Specifications, Section 6.9.4.b, the attached Licensee Event Report is hereby submitted.

Very truly yours,

Monteat (1, antis Herbert A. Autio Plant Superintendent

LDF/amt

Enclosure:

- cc: [30] Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555
 - [3] Director, Office of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555
 - [14] NSARC Chairman
 - [1] Manager of Operational Quality Assurance (YAEC)
 - [1] Institute of Nuclear Power Operations (INPO)
 - [1] Nuclear Safety Analysis Center (NSAC)