



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

2 APR 1981

Docket No. 50-334

Duquesne Light Company
ATTN: Mr. C. N. Dunn
Vice President-Operations Division
435 Sixth Avenue
Pittsburgh, Pennsylvania 15219

Gentlemen:

Subject: Inspection 50-334/80-29


This refers to your letter dated February 13, 1981, in response to our letter dated January 22, 1981.

After careful review we find the action to prevent recurrence for Item 1 is not responsive. Identifying the door as an "unavoidable security hazard" and instructing station personnel to "avoid unauthorized release of the lock on vital area emergency exits" is not considered adequate to prevent recurrence. We consider more positive action to be necessary, such as modification of the door or repositioning of the alarm.

We also note that the date on which compliance will be achieved is March 31, 1981. We do not understand the reason for the time delay in achieving compliance for this item.

You are requested to reevaluate the actions taken to prevent recurrence of Item 1 and determine the reason for the delay in achieving compliance. Please respond to this office within twenty-five (25) days of receipt of this letter.

Sincerely,


Boyce H. Grier
Director

cc:

F. Bissert, Technical Assistant Nuclear
R. Washabaugh, QA Manager
G. Moore, General Superintendent, Power Stations Department
J. J. Carey, Director of Nuclear Operations
J. Werling, Station Superintendent
R. Martin, Nuclear Engineer
J. Sieber, Superintendent of Licensing and Compliance, BVPS

8106040540