

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 50-334/80-29
Docket No. 50-334 License No. DPR-66 Safeguard Group IV

Licensee: sne Light Company
435 Sixth Avenue
Pittsburgh, Pennsylvania 15219

Facility Name: Beaver Valley Power Station, Unit 1

Inspection at: Shippingport, Pennsylvania

Inspection Conducted: November 3-7, 1980

Date of Last Physical Security Inspection: June 16-20, 1980

Type of Inspection: Routine, Unannounced Physical Security

Inspectors: *G. C. Smith*
G. C. Smith, Physical Security Inspector

12-3-80
Date Signed

R. J. Bailey
R. J. Bailey, Physical Security Inspector

12-29-80
Date Signed

Approved by: *J. W. Devlin*
J. W. Devlin, Chief, Security & Investigation
Section, Safeguards Branch

12/31/80
Date Signed

Inspection Summary:

Routine Unannounced Inspection on November 3-7, 1980 (Report No. 50-334/80-29)
Areas Inspected: Security Plan; Security Program Audit; Security Organization;
Physical Barriers (Protected Area), (Vital Areas); Lighting; Access Control
(Identification, Authorization and Badging), (Search), (Escorting), (Vital
Areas); Alarm Stations; Detection Aids; Assessment Aids; Communications;
Testing and Maintenance; Compensatory Measures; Power Supply; Response; Locks,
Keys and Combinations and Records and Reports. The inspectors also reviewed
the licensee's actions taken as a result of items of noncompliance identified
in a previous inspection report and actions taken as a result of a management
meeting on July 18, 1980 outlined in an IAL dated July 21, 1980. The inspection
involved 62 inspector-hours onsite by two NRC regional based inspectors. The
inspection was initiated during regular hours, 6 inspector-hours were accomplished
during off-shift periods.

8106040553

Results: The licensee was found to be in noncompliance with NRC requirements in two (2) of the twenty (20) areas examined. Physical Barriers, one item Paragraph 9 (Failure to control a vital area), Access Control, two items Paragraph 11 (Failure to follow access control procedures, and Paragraph 12 (Failure to follow search procedures).