

Reported \$X2-19-81 Lunda

NA

February 13, 1981

Mr. James G.Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station

Docket No. 50-295/DPR-34

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/81-2 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b(2), which states that any condition leading to plant operation in a degraded mode permitted by a limiting condition for operation requires a 30 day written report.

Very truly yours,

K. L. Graesser Superintendent Zion Station

cc: J. Kohler/J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/81-2

4021/1

FEB 1 7 1981