Midwest Inspection Service, Ltd.

P. O. Box 3081 • Green Bay, Wisconsin 54303 • Telephone: 414/336-3554

May 18,1981

Mr. D.G. Weidman United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

Gentlemen:

In response to your letter dated April 17,1981 RE: License No. 48-16295-01 Midwest Inspection Service, Ltd. routine safety inspection. Midwest Inspection Service, Ltd. submits the following information and statements.

- Item 1. A rewrite of our license for renewal (submitted May 1,1981) will show a deletion of 957 Mancel Lane as corporate headquarters, and a change of address. Permanent Storage containment shall remain stated Attachment 6 (a) page 5 of our license.
- Item 2. 10 CFR 34.28(b) As stated at inspection, this file was misplaced, as I was doing an audit of Midwest Inspection Service, Ltd. that was not completed at time of inspection. Records/Audit is being completed and documentation in proper files.
- Item 3. 10 CFR 34.26 Our quarterly inventory is carried on same report form that we use for quarterly maintenance, and documentation is being completed and put in proper files.

Compliance of Item 1. was achieved May 1,1981. Compliance of Items 2 and 3 shall be accomplished by June 15,1981.

I, Donald Paschen submits the above statements under oath as being true and factual.

Sincerely,

Donald Paschen

DP/ks

STATE OF WISCONSIM
EROWN COUNTY PARENTALEN

AD 1955

AD 1955