

**Transamerica  
Delaval**



Transamerica Delaval Inc.  
Engine and Compressor Division  
550 85th Avenue  
P. O. Box 2161  
Oakland, California 94621  
(415) 577-7400

March 16, 1981

U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

Attn: Mr. Vldis Potapous, Chief  
Vendor Inspection Branch

Gentlemen:

As requested in your letter of March 3, 1981 we are pleased to send you the additional information you require.


Item A:

Corrective Action Request Number 057 was written December 12, 1980. This request discribed the finding, cause, and gave a recommended corrective action. The corrective action implementation by the responsible department was completed December 12, 1980. The Quality Assurance Manager approved the action taken December 16, 1980.

Item C, E, F, G, and I:

Copies of the completed Corrective Action Request forms for Items E, G, F, and I, have been attached to the Internal Audit Check List form for the departments involved. Our internal audit will be conducted and completed during March. A Corrective Action Request was not written for Item C. The internal Audit Check List has been revised to cover review of Weld Inspector qualification and training. IP-600 has been revised to cover the Level II and Level III examination and qualification.

Sincerely,

  
R.E. Boyer  
Manager  
Quality Assurance

8106120283